

Dilapidation Inspection Report

Inspection Details

Date / Time of Inspection:

Type of Report:

Dilapidation Inspection

Address of Property:

Client Details

Client Name:

Client Email Address:

Client Phone:

Client Address:

Real Estate Agent Lotails

Agent Name:

Company:

Mobile:

Email

Insp.ct r Details

Inspector name:

Inspector Office:

Inspector Phone:

Inspector Email Address:

iSPECT

Dilapidation Inspection Report

iSPECI Building Inspections offers property inspection services for your property, by highly qualified inspection experts. Each of the inspectors agrees to comply with and are performance managed against iSPECT's Code of conduct. For further information about your report call 1300 477 328 or for further information on our code of conduct please visit https://ispect.com.au/code-of-conduct



TABLE OF CONTENTS

9

11

34

51

52


- 1. Description of property inspected
- 2. Definitions
- 3. Inspection Agreement
- 4. Terms & Conditions
- 5. External of House
- 6. Internal of house
- 7. Report findings summary
- 8. iSPECT Building Inspections

1. Description of property inspected

Brief description of the building and other structures on the property:

Туре:	Domestic	Freestanding House
Bedrooms:	2	
Bathrooms:	1	
Ensuites:	-	
Car Park:	None	
Height:	Single Story	
Building:	Brick Veneer	
Piers:	Concrete	
Floor:	Slab	
Roof:	Tile	
Age:	2020s	$\langle \rangle$

Image of property:





Weather at time of inspection?

Fine

Was the property furnished at time of inspection?

Yes

Please note: To conduct an inspection in accordance with AS 4349.0 the property would be vacant of all furnishing to enable a thorough visual inspection.

Was there evidence of any extensions at time of inspection?

No

Comment:

Electricity:	Yes	
Comment:		
Gas:	No	
Comment:		
Water:	Yes	
Comment:		
Sewer:	Yes	
Comment:		
	\sim	
Drainage:		
Drainage: Comment:	25	



2. Definitions

Condition Viewally Fines	When the Inspector has viewed the subject area and sees no major structural defect, no
Condition Visually Fine:	minor defect and there is no repair recommended.
General Advice on item:	The Inspector may choose to comment on the subject area, where it doesn't fall into the above categories.
Damage advice on item:	A suggestion that the repair of the defect be carried out by a licenced person, trades per or a person of ability, halting further deterioration to the property.
Major structural Defect:	A defect of sufficient magnitude where repair works must be carried out in order to avoid unsafe conditions, loss of utility or further deterioration of the property.
Unable to Inspect Due to access:	An area of the site where there is insufficient, unsafe or unreasonable access.
Not Applicable (N/A):	N/A: When the subject field doesn't make up any part of the instructeur, every,
Report Definition	
Shower Recesses:	Tests may be made on shower recesses to detect leaks (if where is the weed). The tests not reveal leaks or show incorrect waterproofing silicon liquid or masonry sealant has been applied prior to the inspection. Such application is the morary waterproofing mean and may last for some months before breaking down the tests of shower recesses are limited to running water within the recess and visual checking for leaks. As shower a only checked for a short period of time prolonged use moreveal leaks were not detect at the time of inspection. No evidence of a current leak during inspection does not necessarily mean that the shower does in the ak.
Glass Caution:	Glazing in some building (built before 1978) in coord necessarily comply with current glusafety standards AS1288 with eintreasts of safety, glass panes in doors and windows especially in high traffic and scheme and the intreasts of safety glass of have shatterproof installed.
Stairs & Balustrades:	The Australian Folding Code 3.9 source that covering stairs, landings and balustrades ensure the starty of all occupants and visitors to a building. Those built prior to 1996 man not complement the current standard. You must upgrade all such items.
Swimming Pools:	A pool is subjucto a specific purpose property report and is not applicable to this report
Rooms Below Ground Level:	Roms under the house or below ground level (whether they be habitable or not) may be suble to damp less and water penetration. Drains are not always installed correctly to ese a loss of could be blocked. It is common to have damp problems and water entry lese space, especially during periods of heavy rainfall and may not be evident on the of the visual inspection. These rooms may also not have council approval. The purchase should make their own enquiries to Council to ascertain if approval was granted.
Owners Corporation:	The property is covered by an Owners Corporation (Strata Title) APBI recommend that Owners Corporation search be conducted to ascertain their financial position, the level



3. Inspection Agreement

Requirement for inspection agreement

AS 4349.1 - 2007 requires that an inspection agreement be entered into between the inspector & the client prior to the conduct of the inspection. This agreement sets out specific limitations on the scope of the inspection and on limits that apply in carrying it out. Where specific State or Territory requirements apply in addition to the scope of work in this agreement, or where the inspector and client agree to additional matters being covered, that additional scope is listed at the end of this agreement. It is assumed that the existing use of the building will continue.

AS 4349.1 - 2007 requires that the basis for comparison is a building of similar age and similar type to the subject building ar which is in reasonable condition, having been adequately maintained over the life of the building. This means that building inspected may not comply with Australian Standards, building regulations or specific state or territory requirements applied to the state of the sta cable the time of the inspection.

Purpose of inspection

The purpose of the inspection is to provide advice regarding the condition of the property at the time of the in

Partially furnished only.

Reasonable Access to the property at time of inspection?

Yes

Note:

Areas where reasonable entry is denied to the inspector or where reasonable ess is not able are excluded from and do not form part of the inspection. Access limitations may include legal right of en locked oors, rity system, pets, furniture or other obstructions. Physical access limitations may include height, narrow unda clearance, chick vegetation, small roof or crawl space and adverse weather conditions. The report shall identify any a em with the scope of the inspection that

was not inspected and the factor that prevented inspection.

The extent of accessible areas shall be determined by the inspect encountered at that time. The inspection shall include only accession me o on based on the conditions IT Th sible ar that are within the inspector's line of sight s and ar and close enough to enable reasonable appraisal.

Reasonable access includes a prerequisite that the minimum cle In the table below are safely available. Dimensions for reasonable access:

• Roof Interior: 400mm x 500mm access hole; 600 h x 600mm crawl ce; and accessible from a 3.6m ladder;

nm x 600mm crawl space; and accessible from a 3.6m ladder placed on the Roof exterior: 400mm x 500mm access hole; ground Supplementary notes:

oles or the removal of screws and bolts or any other fastenings or Reasonable access does not include the cutting sealants to access covers.

 Sub-floor areas sprayed with chem are not be in ected unless it is safe to do so.



Conditions

An inspection report may be conditional on:

- Prevailing weather conditions or recent occupancy and use of services that might affect observations.
- Information provided by the client or agents of the client.
- Deliberate concealment of defects.
- Any other relevant factor limiting the inspection.

Scope of inspection

What is not reported on, general exclusions detailed in AS 4349.1 - 2007

- Parts of a building that are under construction;
- The inspection is not intended to include rigorous assessment of all building elements in a property;
- Defects that would only be apparent under particular weather conditions or when using particular fittings & f
- Defects not apparent due to occupancy or occupancy behaviour e.g. non-use of a leaking shower;
- The inspection report is not a certificate of compliance of the property within the requirements of any Act egulat ordinance, local law or by-law and is not a warranty against problems developing with the building in the future
- Unauthorized building work or of work not compliant with building regulations;
- Title and ownership matters, matters concerning easements, covenants, restrictions, zoning cert
- related matters:

• Estimation of the cost of rectification of specific defects.

What is not reported on, specific exclusions detailed in AS 4349.1 - 2007

• Footings below ground, concealed damp-proof course, electrical installations, operation of solve decovers, light switches and fittings, TV, sound and communication and security systems, concealed plumbing adequary of roof drainage as installed, gas fittings and fixtures, air conditioning, automatic garage door mechanisms, swimming poor and associated filtration and similar equipment;

• The operation of fireplaces and solid fuel heaters, including chimneys and udes, alarm systems, intercom systems, soft floor coverings, electrical appliances including dishwashers, incinerators, ovens, udcted violum systems, paint coatings except external protective coatings, health hazards e.g., allergies, soil toxicity, leave ontergradon, presence of asbestos or urea formaldehyde), timber and metal framing sizes and adequacy, concealed tie cours and brong, timber pest activity, other mechanical or electrical equipment (such as gates, inclinators);

mechanical or electrical equipment (such as gates, inclinators); • Soil conditions, control joints, sustainable development provisions, coccaled prong-timbers or any areas concealed by wall linings or sidings, landscaping, rubbish, floor cover, furnitude and accussories, stored items, insulation, environmental matters e.g. BASIX, water tanks, BCA environmental provisions, mergy and the bighting efficiency.

What is reported on

The inspection includes subjective appraisal by an aspector competent assess the condition of residential buildings. It involves a subjective assessment so different inspectors of sven the same inspector on a different occasion may reach different conclusions.

The inspection comprises a visual assessment on the property to dentify major defects and to form an opinion regarding the general condition of the property at the time of inspection. The collowing areas shall be inspected where applicable:

• The interior of the building: ceilin, walls; floors; whereas; doors & frames; kitchen; bathroom; WC; ensuite; laundry; stairs & damp problems;

• The exterior of the building and (inclusing linter, claddings, doors & windows); timber or steel frames & structures; chimneys; stairs; balconies, valuate nation, lector, suspended concrete floors, balustrades;

• The roof exterior: roof / cluding tes, shing a & slates, roof sheeting, gables, flashings); skylights, vents, flues; valleys; guttering; downpipes; eave fasciar and barges;

• The roof space: roof cover the pof framing; sarking; party walls; insulation;

The sub-floor space on the part including supports, floor, ventilation, drainage, damp); suspended concrete floors;
The property within 30 of the puse and within the boundaries of the site: car accommodation, detached laundry, ablution facilities and garden she s; in mining walls (where supporting other structures and landscaping retaining walls > 700mm high);

paths & driven the steps, enched general & swimming pool); surface water (drainage effectiveness).



alľ

r law-

4. Terms & Conditions

APBI Terms & Conditions

General

1. Australian Property and Building Inspections (APBI) has prepared this report in accordance with the guidelines of **Australian Standard 4349.0** – **2007 Inspection of Buildings Part 0: General requirements** (the Standard) which covers the minimum requirements for the visual inspection of buildings and based on the inspection of the property by the Inspector named in the building inspection report.

2. This Standard is used for any of the following inspection purposes:

- Building Defect
- Commercial Building
- Building Dilapidation

3. The Report is prepared for the sole and exclusive use of the Client (person, persons or body) named in Confirmation and cannot be used or acted upon by any other party without the express permission (APBI.

4. The Terms and Conditions are available on the website: www.apbi.com.au and can change with at notice.

5. The Client, having been provided with the opportunity to read these Terms and Condition for the making of a booking and a payment for an inspection, accepts these Terms and Conditions.

6. The Client acknowledges that these Terms and Conditions take precedence over any calor witten representations made by APBI or the Inspector, to the extent of any inconsistency.

7. A report prepared in accordance with the Standard is not a certificate of compliance of the preperty within the requirements of any Act, regulation, ordinance, local law or by-law, or as a warranty or an interance alicy against problems developing with the building in the future.

The Inspection

8. All inspections will be a non-invasive visual inspection and version in the belimit of the those areas and sections of the property to which Reasonable Access (see below) is both available and permitted on the cate and the of Inspection.

9. The inspection is undertaken, and the Report prepared, by the Inspector on the assumption that the existing use of the Inspected Property will continue. As such, the Inspector will not assess the fitness of the Inspected Property for any other intended purpose. We advise you to verify any proposed change in use of the Inspected Property with the relevant authorities.

10. The Inspected Property shall be compared with a briding that was constructed in accordance with the generally accepted practice at the time of construction and which has then maintailed such that there has been no significant loss of strength and serviceability.

Reasonable Access

11. The Standard provides the usars and recognable access" shall be determined by the inspector at the time of the inspection, based on the conditions encountered at the time of inspection. An inspector shall only inspect areas where safe, unobstructed access is provided and when the minimum clearances are available or, where these clearances are not available, areas within the inspector's unobstructed line of size and close enough to enable reasonable appraisal.

12. Minimum clearance is a defined as at least 600mm vertical and horizontal clearance for roof space and sub floor area access. The interior and exterior root must be accessible from a 3.6 metre high ladder for reasonable access to be available.

13. Reasonable access doe not well de removing screws and bolts to access covers. Nor does reasonable access include cutting or making access trapers a pving furniture or stored goods. **Limitations**

sse, the products, toxic mould, Methamphetamine or other substant or water black of a substant or Methamphetamine or other substant of Asbestos dust is a hazardous material and should not be disturbed. It is vital that asbestos is not sawn, when or water blasted, etc. For more information about the handling and disposing of asbestos contact your local

heating and cooling systems, blinds (internal and external), soft furnishings, telephones, spa and pool equipment, building autor tion, electrically operated doors, plant and equipment. Any item not specifically noted in this Report is excluded from the instruction of the Inspected Property. We suggest that a licensed tradesperson be contacted for a separate report in respect of gas or electrical appliance and fittings.

16.No item of furniture or fixtures will be removed, moved or modified during the inspection and items and conditions covered by such furnishings and fixtures are not inspected or considered. Nor do we assess the condition of conspicuous, non-structural items such as carpets, vinyl floor coverings etc.

17. The Inspector can only make comment about the general, visible condition of electrical wiring and plumbing. We suggest that a licensed tradesperson be contacted for a separate report.

The Inspection Report



14. N

harm

andeo ouncil 18. The Report must be read carefully and, in its entirety, to gain a complete understanding of the findings of the inspection of the Inspected Property. It will help you understand the limitations faced by an inspector and why it is not possible to guarantee that a property is completely free of defects.

19. This Report describes the visual assessment of the Inspected Property including: the relevant features of the Inspected Property within 30m of the building and within the boundaries of the site, the prevailing structural, soil and weather conditions at the date and time of the inspection.

20. The Report is a subjective assessment of the Inspected Property and therefore outlines the opinion of the Inspector on the general condition of the Inspected Property at the date and time of the inspection in relation to major defects or safety hazards and a general advice on minor defect items.

21. The Report does not cover any part of the building located beneath the ground surface or identify any unauthorised bu work or of work not compliant with building regulations.

22. An estimate of the costs of rectification of defects is not required in accordance with the Standard.

23. Any maintenance and general advice items are intended as a helpful guide. The Report is not an exhaustive c of all maintenance and advice items.

24. The Report provides no guarantee and is not a warranty against problems developing with the Inspected Proplet in the future.

25. This Report is not a rigorous assessment of all building elements and does not cover all maintenince items. This Report also does not cover defects in inaccessible areas, defects that are not reasonably visible, defects that my only be appendin certain weather conditions or defects that have not yet arisen due to prolonged periods of wet or dryweather or other subsequent events.

26. This Inspection Report does not identify the presence of timber pests, or any dampe caused by timber pests (e.g. termites, borers, etc.). If you wish to include this, you will need to request a Timber Pest inspection report. If there is a concern regarding other types of pests then a fully qualified Pest Controller should be contacted.

Other matters

27. You should address legal and conveyancing matters such as title and own of a to your plicitor or legal representative. Compliance issues in relation to the positioning of services, privacy of the access the sing of the buildings, zoning, permit or town planning issues or other legal matters should be directed to be relevant autovition to a solicitor or legal representative.

28. Unless otherwise notified, Australian Property & Building Interction and Property available to prospective buyers. Please advise within 48 hours of receipt of the property if, as a vendor, you do not wish this report to be made available to prospective purchasers of the property.



	Condition Visually Fine	General Advice On Item	Damage advice on Item	Major structural Defect	Unable to Inspect Due to Access	Not Applicable
Driveways and Paths			đ			
Walls			đ			
Expansion joints	V					
Windows			đ			
Window Placement	√					
Doors			র্থ			
Fascia	d					
Eaves		ď				
Flashings						∑
Roof		ď				
Skylights						₫
Vents	ď					
Valleys		ď				
Down Pipes	ď					
Drainage	√					
Pointing	√					
Gutters						
Chimney						J
Sub Floor Ventilation						V
Deck						V
Pergola						V
Porc		V				
Balcony						V
5.						V
h vails						V
Pool pace					V	
Jtumps						d
Retaining Walls		J				
Garage/Car Port						V



External of Property

Damage advice on Item

Driveways and paths

Comments

Loose paver finish path to the grannyflat.


Cracking to concrete path present.


Moss and discolouration to path present.

Main house driveway, cross over and kerb presenting cracking and damage.































































































External of Property Retaining Walls General Advice On Item Comments Significant Moss and moisture to retaining walls, gaps present to the right hand side.



6. Internal of house

Internal of property inspection checklist

	Condition Visually FINE	General Advice on Item	Damage advice on item	Major structural Defect	Unable to Inspect Due to access	Not Applicable (N/A)
Entry/Hallway						Image: A start of the start
Lounge Room			 ✓ 			
Family Room						
Kitchen		 ✓ 				
Bedroom 1		 ✓ 				
Bedroom 2		 ✓ 				
Bedroom 3						
Bedroom 4						
Bedroom 5		v				
Bathrooms						
Ensuite						
Laundry						
Stairs						✓
Handrails						v



C

Internal areas

Damage advice on Item

Family Room

Comments


This is family room/lounge room and hallway combined due to open plan.

Visible wear and tear present to surfaces.


Cracking to adjoining walls/surfaces, skirting, architraves and to cornice joints.

Storage cupboard right side binding onto the panel.















Internal areas

Damage advice on Item

Lounge Room

Comments


This is family room/lounge room and hallway combined due to open plan.

Visible wear and tear present to surfaces.


Cracking to adjoining walls/surfaces, skirting, architraves and to cornice joints.

Storage cupboard right side binding onto the panel.















Internal areas **General Advice On Item** Kitchen Comments Visible wear and tear present to surfaces. Cracking to adjoining walls/surfaces, skirting, architraves and to cornice joints.

Internal areas

Damage advice on Item

Bedroom 1


Comments


Visible wear and tear present to surfaces.

Cracking to adjoining walls/surfaces, skirting, architraves and to cornice joints.

Robe rubbers damaged.

















Internal areas

Damage advice on Item

Bedroom 2


Comments


Visible wear and tear present to surfaces.

Cracking to adjoining walls/surfaces, skirting, architraves and to cornice joints.

Draw issue to robe area.

















Internal areas Major Structural Defect Bathrooms

Comments

Visible wear and tear present to surfaces.

Significant cracking to grout joints in multiple areas of the shower recess.


Door handle shifted and not straight.

Discolouration of shower recess grate.

Tap loose.


























7. Report findings - summary

This Building Inspection summary provides you with a "snapshot" of the items the inspector considers of greatest significance for you, in respect of the building only, when considering this property. Please refer to the Definitions and the complete Report for detailed information regarding visible defects. Note that this Summary is not the complete Report and that in the event of an apparent discrepancy the complete Report overrides the Summary information.

Report Summary

All states in the report.

Major Defects noted

Yes

A defect of sufficient magnitude where rectification has to be carried out with out ordue delete to avoid: unsafe conditions, posing a threat to life or serious injury; loss of utility, whereby the defect is such that the whole of the relevant part of the building can no longer serve its intended function; or further substantial deterioration of the building can be building.

Shower recess cracking to grout lines.

Serious Structural efects loted

No

A major defecting any internal, external primary load bearing component of the building which seriously affects the structural integrity of the scribbing requiring pectification to be carried out without undue delay to avoid: unsafe conditions, posing a threat to life or serious injugue loss of utility, whereby the defect is such that the whole of the relevant part of the building can no longer serve its intended unction of further substantial deterioration of the building. In the case of cracking, a serious structural defect denote serve cracking as defined by Category 4, Appendix C – Australian Standard AS 2870-2011. Appendix C is attached for your offension.



8. iSPECT Building Inspections

The iSPECT Building Inspections is a national franchise building inspections business. iSPECT engages with trade qualified builders with a minimum of 10 years residential and commercial building experience to complete property inspections. Each home and building inspection completed is then detailed in a report that is completed to Australian Standards AS4349.0, AS4349.1 and/or AS4349.3. iSPECT has franchise nationally who are supported by a national call centre located at 8 Aprerso Street, Port Melbourne. Our office locations follow:

