

Warranty (Defect) inspection report

Inspection Details

Date / Time of Inspection:

Type of Report:

Warranty (Defect) inspection

Address of Property:

Client Details

Client Name:

Client Email Address:

Client Phone:

Real Estate Agen. Dr cails

Agent Name:

Company:

Mobile:

Email Address:

Inspector Details

Inspector Name **Inspector Office: Inspector Phone: Inspector Email Address:**

iSPECT

Warranty (Defect) inspection report

iSPECT Building Inspections offers property inspection services for your property, by highly qualified inspection experts. Each of the inspectors agrees to comply with and are performance managed against iSPECT's Code of conduct. For further information about your report call 1300 477 328 or for further information on our code of conduct please visit https://ispect.com.au/code-of-conduct



TABLE OF CONTENTS

1. Description of property	
2. Definitions	
3. Inspection Agreement	7
4. Terms & Conditions	9
5. Hallways and general living spaces	11
6. Kitchen	15
7. Laundry	18
8. Bedrooms	20
8.1. Bedroom 1	20
8.2. Bedroom 2	23
8.3. Bedroom 3	25
8.4. Bedroom 4	27
9. Bathrooms	28
9.1. Bathroom 1	28
10. Ensuite	30
10.1. Ensuite 1	30
11. External of property > Exterior	32
12. External of property > Roof areas	41
13. External of property > Sub flow areas	44
14. Findings and summary	45
15. iSPECT Building Inspections	46

Shi

1. Description of property

Brief description of the building and other structures on the property:

Туре:	Freestanding House	Domestic
Bedrooms:	4	
Bathrooms:	1	
Ensuites:	1	
Car Park:	Double	
Height:	Two Story	
Building:	Brick Veneer	
Piers:	Concrete	
Floor:	Timber with concrete areas	
Roof:	Tile	$\gamma \nabla$
Age:	New build	

Image of property:





Weather at time of inspection?

Fine

Was the property furnished at time of inspection?

Yes

Please note: To conduct an inspection in accordance with AS 4349.1 the property would be vacant of all furnishing to enable a thorough visual inspection.

Was there evidence of any extensions at time of inspection?

No

Comment:

Electricity:	Yes		
Comment:		\mathbf{V}^{-}	
Gas:	Yes		
Comment:			
Water:	Yes		
Comment:			
Sewer:	Yes		
Comment:			
Drainage:		 	
Comment:	N		
Smoke Detect.	es		
Compare:			



2. Definitions

Condition Visually Fine:	When the Inspector has viewed the subject area and sees no major defect, and sees no safety hazard.
Minor and/or Major Defect	Any defect observed to the property in accordance with the Standards and Tolerances where applicable, where repair works must be carried out. Repairs should be carried out a suitably qualified or licenced trades person.
Incomplete Item	Any item that is deemed incomplete at the time of the inspection, but not channed defeat that time.
Unable to Inspect Due to Access	An area of the site where there is insufficient, unsafe or unrease able actors.
Not Applicable (N/A):	When the subject field doesn't make up any part of the inspected property.
Report Definition	
Shower Recesses:	Tests may be made on shower recesses to detect leads towater is connected). The tests in not reveal leaks or show incorrect waterphofing if sin an liquid or masonry sealant has been applied prior to the inspection. Such application is emporary waterproofing measure and may last for some months before reaking town. The ests of shower recesses are limited to running water within the reaches and visually checking for leaks. As shower an only checked for a short period of time, propaged using y reveal leaks were not detected at the time of inspection. No construct of a consent toak during inspection does not necessarily mean that the shower of us not lead
Glass Caution:	Glazing in some building (build nore 1976) may not necessarily comply with current glass safety standards AS1288. In the sterests of safety, glass panes in doors and windows especially in high traffic areas should be replaced with safety glass of have shatterproof finstalled.
Stairs & Balustrades:	The Auster on Built of Code 3.9 require that covering stairs, landings and balustrades ensure the determal occupants and visitors to a building. Those built prior to 1996 may not comply which current standard. You must upgrade all such items.
Swimming Pools:	A pol is subject to a special purpose property report and is not applicable to this report.
Rooms Below Ground Level	boms using the house or below ground level (whether they be habitable or not) may be ubject to dampness and water penetration. Drains are not always installed correctly to these areas or could be blocked. It is common to have damp problems and water entry in these spaces, especially during periods of heavy rainfall and may not be evident on the d of the visual inspection. These rooms may also not have council approval. The purchaser hould make their own enquiries to Council to ascertain if approval was granted.
Owners Corporation.	If the property is covered by an Owners Corporation (Strata Title) APBI recommend that a Owners Corporation search be conducted to ascertain their financial position, the level o maintenance afforded and any other relevant information that may impact your future ownership of the property.
5	



3. Inspection Agreement

Requirement for inspection agreement

AS 4349.1 - 2007 requires that an inspection agreement be entered into between the inspector & the client prior to the conduct of the inspection. This agreement sets out specific limitations on the scope of the inspection and on limits that apply in carrying it out. Where specific State or Territory requirements apply in addition to the scope of work in this agreement, or where the inspector and client agree to additional matters being covered, that additional scope is listed at the end of this agreement. It is assumed that the existing use of the building will continue.

AS 4349.1 - 2007 requires that the basis for comparison is a building of similar age and similar type to the subject building an which is in reasonable condition, having been adequately maintained over the life of the building. This means that building a inspected may not comply with Australian Standards, building regulations or specific state or territory requirements approable the time of the inspection.

Purpose of inspection

The purpose of the inspection is to provide advice regarding the condition of the property at the time of the inspection of the time of the time

Reasonable Access to the property at time of inspection?

Yes

Note:

Areas where reasonable entry is denied to the inspector or where reasonable access is not periable are excluded from and do not form part of the inspection. Access limitations may include legal right of entry tocked doon becurity system, pets, furniture or other obstructions. Physical access limitations may include height, narrow be andary dearant, which we getation, small roof or crawl space and adverse weather conditions. The report shall identify any rea or it or within the scope of the inspection that was not inspected and the factor that prevented inspection.

The extent of accessible areas shall be determined by the inspector at the time, unspective based on the conditions encountered at that time. The inspection shall include only accessible areas and that time are within the inspector's line of sight and close enough to enable reasonable appraisal.

Reasonable access includes a prerequisite that the minimum enances pecified in the table below are safely available. Dimensions for reasonable access:

• Roof Interior: 400mm x 500mm access hole; 600mm x 600mm crain space; and accessible from a 3.6m ladder;

• Roof exterior: 400mm x 500mm access hole; 600m in x 600mm crawle ace; and accessible from a 3.6m ladder placed on the ground

Supplementary notes:

• Reasonable access does not include the cutting paccess hows or the removal of screws and bolts or any other fastenings or sealants to access covers.

• Sub-floor areas sprayed with chemicals are not be up and unless it is safe to do so.



Conditions

An inspection report may be conditional on:

- Prevailing weather conditions or recent occupancy and use of services that might affect observations.
- Information provided by the client or agents of the client.
- Deliberate concealment of defects.
- Any other relevant factor limiting the inspection.

Scope of inspection

What is not reported on, general exclusions detailed in AS 4349.1 - 2007

- Parts of a building that are under construction;
- The inspection is not intended to include rigorous assessment of all building elements in a property;
- Defects that would only be apparent under particular weather conditions or when using particular fittings & f
- Defects not apparent due to occupancy or occupancy behaviour e.g. non-use of a leaking shower;
- The inspection report is not a certificate of compliance of the property within the requirements of any Act egulat ordinance, local law or by-law and is not a warranty against problems developing with the building in the future
- Unauthorized building work or of work not compliant with building regulations;
- Title and ownership matters, matters concerning easements, covenants, restrictions, zoning cert
- related matters:

• Estimation of the cost of rectification of specific defects.

What is not reported on, specific exclusions detailed in AS 4349.1 - 2007

• Footings below ground, concealed damp-proof course, electrical installations, operation of solve decovers, light switches and fittings, TV, sound and communication and security systems, concealed plumbing adequary of roof drainage as installed, gas fittings and fixtures, air conditioning, automatic garage door mechanisms, swimming poor and associated filtration and similar equipment;

• The operation of fireplaces and solid fuel heaters, including chimneys and udes, alarm systems, intercom systems, soft floor coverings, electrical appliances including dishwashers, incinerators, ovens, udcted violum systems, paint coatings except external protective coatings, health hazards e.g., allergies, soil toxicity, leave ontergradon, presence of asbestos or urea formaldehyde), timber and metal framing sizes and adequacy, concealed tie cours and brong, timber pest activity, other mechanical or electrical equipment (such as gates, inclinators);

mechanical or electrical equipment (such as gates, inclinators); • Soil conditions, control joints, sustainable development provisions, coccaled prong-timbers or any areas concealed by wall linings or sidings, landscaping, rubbish, floor cover, furnitude and accussories, stored items, insulation, environmental matters e.g. BASIX, water tanks, BCA environmental provisions, mergy and the bighting efficiency.

What is reported on

The inspection includes subjective appraisal by an aspector competent assess the condition of residential buildings. It involves a subjective assessment so different inspectors of sven the same inspector on a different occasion may reach different conclusions.

The inspection comprises a visual assessment on the property to dentify major defects and to form an opinion regarding the general condition of the property at the time of inspection. The collowing areas shall be inspected where applicable:

• The interior of the building: ceilin, walls; floors; whereas; doors & frames; kitchen; bathroom; WC; ensuite; laundry; stairs & damp problems;

• The exterior of the building and (inclusing linter, claddings, doors & windows); timber or steel frames & structures; chimneys; stairs; balconies, valuate nation, lector, suspended concrete floors, balustrades;

• The roof exterior: roof / cluding tes, shing a & slates, roof sheeting, gables, flashings); skylights, vents, flues; valleys; guttering; downpipes; eave fasciar and barges;

• The roof space: roof cover the pof framing; sarking; party walls; insulation;

The sub-floor space on the part including supports, floor, ventilation, drainage, damp); suspended concrete floors;
The property within 30 of the puse and within the boundaries of the site: car accommodation, detached laundry, ablution facilities and garden she s; in mining walls (where supporting other structures and landscaping retaining walls > 700mm high);

paths & driven the steps, enched general & swimming pool); surface water (drainage effectiveness).



alľ

r law-

4. Terms & Conditions

APBI Terms & Conditions

General

1. iSPECT Building Inspections (iSPECT) has prepared this report in accordance with the guidelines of **Australian Standard 4349.1** – **2007 Inspection of buildings Part 1: Pre-purchase inspections - Residential Buildings** (the Standard) which covers the minimum requirements for the visual inspection of residential buildings and based on the inspection of the property by the Inspector named in the building inspection report.

2. The Report is prepared for the sole and exclusive use of the Client (person, persons or body) named in the Booking Confirmation and cannot be used or acted upon by any other party without the express permission of iSPECT.

3. The Terms and Conditions are available on the website: www.iSPECT.com.au and can change without notice.

4. The Client, having been provided with the opportunity to read these Terms and Conditions following the mong of a and a payment for an inspection, accepts these Terms and Conditions.

5. The Client acknowledges that these Terms and Conditions take precedence over any oral or writter iSPECT or the Inspector, to the extent of any inconsistency.

6. A report prepared in accordance with the Standard is not a certificate of compliance of the property within the equirements of any Act, regulation, ordinance, local law or by-law, or as a warranty or an insurance policy against publems developing with the building in the future.

The Inspection

7. All inspections will be a **non-invasive visual** inspection and will be limited to the search and sections of the property to which Reasonable Access (see below) is both available and permitted on the date application.

8. The inspection is undertaken, and the Report prepared, by the Inspector on the an umption that the existing use of the Inspected Property will continue. As such, the Inspector will not assess the fit is and the Inspected Property for any other intended purpose. We advise you to verify any proposed change in under the Inspected Property with the relevant authorities.

9. Where the Inspected Property is a unit or apartment (Strata T re), inspected areas will be limited to the nominated residence and does not include common property. i.e. Only those items is not on the relationshall be reported.

10. The Inspected Property shall be compared with a building that the constructed in accordance with the generally accepted practice at the time of construction and which has been maintained such that there has been no significant loss of strength and serviceability.

Reasonable Access

11. The Standard provides that "safe and reasonable occess" shall be determined by the inspector at the time of the inspection, based on the conditions encountered at the time of a pectic. An inspector shall only inspect areas where safe, unobstructed access is provided and where the minimum clearances in available or, where these clearances are not available, areas within the inspector's unobstructed line of sight a close enough to enable reasonable appraisal.

12. Minimum clearances are channed, at least 600 min vertical and horizontal clearance for roof space and sub floor area access. The interior and exterior room must be access by from a 3.6 metre high ladder for reasonable access to be available.

13. Reasonable access loes in signade removing screws and bolts to access covers. Nor does reasonable access include cutting or making access transmoving writting or stored goods.

Limitations

14. **No assess** the **ride tification** is made of asbestos or asbestos related products, toxic mould, Methamphetamine or other harmful substances. As the substances is a hazardous material and should not be disturbed. It is vital that asbestos is not sawn, sanded, drilled or other blasted, etc. For more information about the handling and disposing of asbestos contact your local could be

15. Our application we not assess the operation of appliances, alarms, security and communication systems, smoke detectors, heating the cooling systems, blinds (internal and external), soft furnishings, telephones, spa and pool equipment, building automation, electrically operated doors, plant and equipment. Any item not specifically noted in this Report is excluded from the inspection of the Inspected Property. We suggest that a licensed tradesperson be contacted for a separate report in respect of gas a recent report in contact of the Inspected Property.

16. Notem of furniture or fixtures will be removed, moved or modified during the inspection and items and conditions covered to the furnishings and fixtures are not inspected or considered. Nor do we assess the condition of conspicuous, non-structural items such as carpets, vinyl floor coverings etc.

17. The Inspector can only make comment about the general, visible condition of electrical wiring and plumbing. We suggest that a licensed tradesperson be contacted for a separate report.

The Inspection Report

18. The Report must be read carefully and, in its entirety, to gain a complete understanding of the findings of the inspection of the Inspected Property. It will help you understand the limitations faced by an inspector and why it is not possible to guarantee that a property is completely free of defects.



oking

nade by

ati

19. This Report describes the visual assessment of the Inspected Property including: the relevant features of the Inspected Property within 30m of the building and within the boundaries of the site, the prevailing structural, soil and weather conditions at the date and time of the inspection.

20. The Report is a subjective assessment of the Inspected Property and therefore outlines the opinion of the Inspector on the general condition of the Inspected Property at the date and time of the inspection in relation to major defects or safety hazards and a general advice on minor defect items.

21. The Report does not cover any part of the building located beneath the ground surface or identify any unauthorised building work or of work not compliant with building regulations.

22. An estimate of the costs of rectification of defects is not required in accordance with the Standard.

23. Any maintenance and general advice items are intended as a helpful guide. The Report is not an exhaustive list of all maintenance and advice items.

24. The Report provides no guarantee and is not a warranty against problems developing with the Inspected Profuture.

25. This Report is not a rigorous assessment of all building elements and does not cover all maintenance items. It is Provide that does not cover defects in inaccessible areas, defects that are not reasonably visible, defects that may only be apprend in certain weather conditions or defects that have not yet arisen due to prolonged periods of wet or dry weather we

26. The Building or Pre-purchase Inspection Report does not identify the presence of timber pests, any damage aused by timber pests (e.g. termites, borers, etc.). If you wish to include this, you will need to request a Timber Pest inspection report. If there is a concern regarding other types of pests then a fully qualified Pest Controller shows by post and a set.

Other matters

27. You should address legal and conveyancing matters such as title and owners of to your micitor or legal representative. Compliance issues in relation to the positioning of services, privacy, vehicle access, the siting of the buildings, zoning, permit or town planning issues or other legal matters should be directed to the relevant authority or to a micitor or legal representative.

28. Unless otherwise notified, iSPECT Building Inspections will make vendor producted reports available to prospective buyers. Please advise within 48 hours of receipt of this report if, as a vendor of the notion of this port to be made available to prospective purchasers of the property.



5. Hallways and general living spaces





	Condition Visually Fine	Minor and/or Major Defect	Incomplete Item	Unable to Lapect Due	rt Applicable (N/A)
Floor	۷				
Walls	র্থ				
Ceilings		đ			
Doors		đ			
Windows	র্থ				
Fireplace					Ŋ
Stairs					
Balustrade					

Ċţ.









6. Kitchen





	Condition Visually Fine	Minor and/or Major Defect	Incomplete Item	Unable to hanect Due teasce.	ot Applicable (N/A)
Floor	đ				
Walls	đ				
Ceilings	Ţ				
Doors	√				
Windows					
Cabinets / Drawers		Ø			
Benchtops	đ				
Sink/Taps	√				
Appliances (Oven, Range Hood, Dishwasher)					
Ventilation					



Shr







7. Laundry





	Condition Visually Fine	Minor and/or Major Defect	Incomplete Item	Unable to In the Due to sce.	ot Applicable (N/A)
Floor	۷				
Walls	ъ				
Ceilings	ъ				
Doors		V			
Windows	ъ				
Trough/Sink		Ø			
Taps	ъ				
Cabinets	ъ				
Sealants	1				
Exhaust Fans					
Ventilation					



St

Laundry

Minor and/or Major Defect

Trough/Sink

Comments

Sink has high spots due to tight fit, bench top cut put to small for laundry sink, not sitting flush with benchtop. Needs rectifying.






Laundry

Minor and/or Major Defect

Comments

Cavity slidedoor touches bottom guide when closing door, when for touches guide comes out of position for a moment. Guide needs to be placed slight forward to avior mis problem.








8. Bedrooms

8.1. Bedroom 1





	Condition Visually Fine	Minor and/or Major Defect	Incomplete Item	able to nspect t/ access	Not Applicable (N/A)
Floor	র্থ				
Walls	d				
Ceilings	র্থ				
Doors					
Windows	র্থ				
Robes					
Smoke Detectors		\mathbf{V}			Ţ



Ç







8.2. Bedroom 2





	Condition Visually Fine	Minor and/or Major Defect	Incomplete Item	Unable to Depect Due	ot Applicable (N/A)
Floor	đ				
Walls	đ				
Ceilings	J		5.		
Doors	√				
Windows					
Robes		₫			
Smoke Detectors					V
Comments Window seal coming o	outerpositio				



Bedroom 2 Minor and/or Major Defect Robes Comments Example, of wardrobe slide doors not sitting square, wall level fine. Looks like bad door installation. Also door coming off bottom track and changing track areas. Rough installation, needs rectifying.



8.3. Bedroom 3





	Condition Visually Fine	Minor and/or Major Defect	Incomplete Item	Unable to lespect Due to Actors	ot Applicable (N/A)
Floor		đ			
Walls	đ				
Ceilings	đ				
Doors	đ				
Windows	đ				
Robes	đ				
Smoke Detectors					J
Comments Example of high area	on ladroom por.				
2					







8.4. Bedroom 4





	Condition Visually Fine	Minor and/or Major Defect	Incomplete Item	Unable to Espect Due)t Applicable (N/A)
Floor	۷				
Walls	J				
Ceilings	J				
Doors	۷				
Windows					
Robes	∑				
Smoke Detectors					J
			÷		

Bedroom 4

Minor and/or Major Defect

Windows

Comments

Customer struggling to open and case blingers feels cord is short. Would like cord extended. Advised installation following legislation and estaller his way to aviod creating a loop, for safety reasons.







9. Bathrooms

9.1. Bathroom 1





	Condition Visually Fine	Minor and/or Major Defect	Incomplete Item	' able to nspect t' access	Not Applicable (N/A)
Floor	র্থ				
Walls	র্থ				
Ceilings	d				
Doors	d				
Windows	J				
Shower Recess	J				
Shower Screen	J				
Shower Rose	☑				
Bath	π				
Taps					
Cabinets					
Sealants					
Basiı.	2				
Toilet		đ			
\ ntilə'	V				
5					







10. Ensuite

10.1. Ensuite 1





	Condition Visually Fine	Minor and/or Major Defect	Incomplete Item	' able to inspect t' access	Not Applicable (N/A)
Floor	র্থ		Ţ		
Walls	র্থ				
Ceilings		V			
Doors	V				
Windows	V				
Shower Recess	V				
Shower Screen	V				
Shower Rose	☑				
Bath					J
Taps	☑				
Cabinets					
Sealants					
Basiı.					
Toilet	▼				
l ntila'	₫				









11. External of property > Exterior

	Condition Visually Fine	Minor and/or Major Defect	Incomplete Item	Unable to Inspect Due to Access	Not Applicable (N/A)			
Walls		Ŋ						
Windows		đ						
Doors		Ŋ						
Fascia, Eaves, Bargeboards	র্থ							
Down Pipes	J							
Deck, Verandah, Balcony, Patio		Ŋ						
Steps	র্থ							
Handrails				Ĺ	M			
Pergola								
Driveways and Paths	র্থ							
Retaining Walls	র্থ							
Garage/Car Port		Ŋ						

External > Exterior

Minor and/or Major Defect

Garage/Car Port

Comments

Garage second entry door handle faulty and not working, needs replacing. Same area bottom aluminium sill rusting on either end.

















External > Exterior

Minor and/or Major Defect

Comments

Front light not working bottom section



-









External > Exterior

Minor and/or Major Defect

Comments

Owner concerned that screw / bolts not supporting brackets properly as installed in the centre of opening rather than up top.

-











SPECT

12. External of property > Roof areas

Roof Type: Timber truss






	Condition Visually Fine	Minor and/or Major Defect	Incomplete Item	nable transpect Due • Access	Not Applicable (N/A)
Roof Space		Ŋ	Γ		
Roof					
Valleys					
Flashings	J				
Gutters	J				
Pointing	J				
Skylights					Ŋ
Vents					Ŋ
Chimney					Ŋ




Shr











14. Findings and summary

This Building Inspection summary provides you with a "snapshot" of the items the inspector considers of greatest significance for you, in respect of the building only, when considering this property. Please refer to the Definitions and the complete Report for detailed information regarding visible defects. Note that this Summary is not the complete Report and that in the event of an apparent discrepancy the complete Report overrides the Summary information.

Report Summary

Overall the property has come together well, no major defects were noted at the time of inspection, items needing attention mentioned in report.

Major Defects Noted

No

A defect of sufficient many de whose rectification has to be carried out without undue delay to avoid: unsafe conditions, posing a threat to lifteer serious bjury loss of utility, whereby the defect is such that the whole of the relevant part of the building can no longer serve the many ded another substantial deterioration of the building.

Major tructural Defects Noted

afor defect in any internal or external primary load bearing component of the building which seriously affects the structural integrity of the building requiring rectification to be carried out without undue delay to avoid: unsafe conditions, posing a threat to life or serious injury; loss of utility, whereby the defect is such that the whole of the relevant part of the building can no longer serve its intended function; or further substantial deterioration of the building. In the case of cracking, a serious structural defect denotes severe cracking as defined by Category 4, Appendix C – Australian Standard AS 2870-2011. Appendix C is attached for your reference.



15. iSPECT Building Inspections

The iSPECT Building Inspections is a national franchise building inspections business. iSPECT engages with trade qualified builders with a minimum of 10 years residential and commercial building experience to complete property inspections. Each home and building inspection completed is then detailed in a report that is completed to Australian Standards AS4349.0, AS4349.1 and/or AS4349.3. iSPECT has franchise nationally who are supported by a national call centre located at 8 Aprerso Street, Port Melbourne. Our office locations follow:

